



## Product Change Notification

Geneva, 23<sup>rd</sup> October 2017

**PCN n°: PCN-012\_2017\_4-OMTS1701801 & S1701802**

**Supplier for plastic parts and some machining**

**LV100 and LV100xx series – Date code LV 100-4200**

Based on the JEDEC JESD46 standard (latest release)

Not for publication unless permission is granted by LEM

Dear customer,

To answer to continuous market requirement for improved performances, and in a permanent effort to improve the quality of its products, LEM intends to proceed to some modification on **LV100 and LV100xx series**.

This letter is to notify you about our planned procedure to handle this change.

we confirm you that LEM is now producing the model **LV 100-4200**, according to the **Change 1** explained here after, and since the **date code 117296**.

Explanation on the date code 117296:

- ❑ “1” means the production center, here LEM in Geneva (Switzerland)
- ❑ “17” means the year of the production, here the year 2017
- ❑ “296” means the day of the production, here the 296<sup>th</sup> day of the year 2017 (23<sup>rd</sup> October 2017)

### Changes:

#### ➤ *Description of the technical changes:*

#### Change 1:

Plastic parts supplier (case, base, winding bodies, clips).

The plastic materials stay the same as before. The moulds stay the same as before

#### **Concerned products for Change 1:**

**LA 10-I/SP8;**

**LV 100;**

**LV 100/SP16; LV 100/SP17;**

**LV 100/SP25;**

**LV 100/SP3; LV 100/SP38;**

**LV 100/SP41; LV 100/SP47; LV 100/SP48;**

**LV 100/SP51; LV 100/SP58; LV 100/SP59;**

**LV 100/SP60; LV 100/SP66; LV 100/SP67; LV 100/SP69;**

**LV 100/SP71; LV 100/SP72; LV 100/SP73; LV 100/SP77; LV 100/SP78; LV 100/SP79;**

LV 100/SP80; LV 100/SP81; LV 100/SP82;

LV 100-50;

LV 100-100;

LV 100-150; LV 100-150/SP4;

LV 100-200;

LV 100-250/SP5; LV 100-250/SP6;

LV 100-300; LV 100-300/SP9;

LV 100-400; LV 100-400/SP8;

LV 100-500; LV 100-500/SP6;

LV 100-600; LV 100-600/SP6; LV 100-600/SP9;

LV 100-750; LV 100-750/SP4; LV 100-750/SP5; LV 100-750/SP7; LV 100-750/SP8; LV 100-750/SP9;

LV 100-800;

LV 100-1000; LV 100-1000/SP2; LV 100-1000/SP9;

LV 100-1000/SP13; LV 100-1000/SP16; LV 100-1000/SP17;

LV 100-1000/SP20; LV 100-1000/SP22; LV 100-1000/SP23;

LV 100-1000/SP24; LV 100-1000/SP25; LV 100-1000/SP26; LV 100-1000/SP29;

LV 100-1200; LV 100-1200/SP8;

LV 100-1500; LV 100-1500/SP3; LV 100-1500/SP4; LV 100-1500/SP7;

LV 100-1600/SP3; LV 100-1600/SP4;

LV 100-2000; LV 100-2000/SP4; LV 100-2000/SP5; LV 100-2000/SP6;

LV 100-2000/SP10; LV 100-2000/SP11; LV 100-2000/SP12;

LV 100-2000/SP15; LV 100-2000/SP17; LV 100-2000/SP18; LV 100-2000/SP19;

LV 100-2500; LV 100-2500/SP3;

LV 100-3000; LV 100-3000/SP11; LV 100-3000/SP12; LV 100-3000/SP15; LV 100-3000/SP3;

LV 100-3500; LV 100-3500/SP2;

LV 100-4000; LV 100-4000/SP2; LV 100-4000/SP3; LV 100-4000/SP6; LV 100-4000/SP9;

LV 100-4000/SP12; LV 100-4000/SP15;

LV 100-4200;

LV 100-5000/SP1;

we confirm you that LEM is now producing **some of the models, listed here above according to the change 1** explained on page 1 and since the following date codes:

- date code **817155 for the following models:**

LV 100-50;

LV 100-100;

LV 100-150; LV 100-150/SP4;

LV 100-200;

LV 100-250/SP5; LV 100-250/SP6;

LV 100-300; LV 100-300/SP9;

LV 100-400; LV 100-400/SP8;  
LV 100-500; LV 100-500/SP6;  
LV 100-600; LV 100-600/SP6; LV 100-600/SP9;  
LV 100-750; LV 100-750/SP4; LV 100-750/SP5; LV 100-750/SP7; LV 100-750/SP8; LV 100-750/SP9;  
LV 100-800;  
LV 100-1000; LV 100-1000/SP2; LV 100-1000/SP9;  
LV 100-1000/SP13; LV 100-1000/SP16; LV 100-1000/SP17;  
LV 100-1000/SP20; LV 100-1000/SP22; LV 100-1000/SP23;  
LV 100-1000/SP24; LV 100-1000/SP25; LV 100-1000/SP26; LV 100-1000/SP29;  
LV 100-1200; LV 100-1200/SP8;  
LV 100-1500; LV 100-1500/SP3; LV 100-1500/SP4; LV 100-1500/SP7;  
LV 100-1600/SP3; LV 100-1600/SP4;  
LV 100-2000; LV 100-2000/SP4; LV 100-2000/SP5; LV 100-2000/SP6;  
LV 100-2000/SP10; LV 100-2000/SP11; LV 100-2000/SP12;  
LV 100-2000/SP15; LV 100-2000/SP17; LV 100-2000/SP18; LV 100-2000/SP19;  
LV 100-2500; LV 100-2500/SP3;  
LV 100-3000; LV 100-3000/SP11; LV 100-3000/SP12; LV 100-3000/SP15; LV 100-3000/SP3;  
LV 100-3500; LV 100-3500/SP2;  
LV 100-4000; LV 100-4000/SP2; LV 100-4000/SP3; LV 100-4000/SP6; LV 100-4000/SP9;  
LV 100-4000/SP12; LV 100-4000/SP15;  
LV 100-5000/SP1;

- date code 817206 for the following models:

LA 10-I/SP8;  
LV 100;  
LV 100/SP16; LV 100/SP17;  
LV 100/SP25;  
LV 100/SP3; LV 100/SP38;  
LV 100/SP41; LV 100/SP47; LV 100/SP48;  
LV 100/SP51; LV 100/SP58; LV 100/SP59;  
LV 100/SP60; LV 100/SP66; LV 100/SP67; LV 100/SP69;  
LV 100/SP71; LV 100/SP72; LV 100/SP73; LV 100/SP77; LV 100/SP78; LV 100/SP79;  
LV 100/SP80; LV 100/SP81; LV 100/SP82;

Just few explanation on the date code (example with date code 817206):

- ❑ “8” means the production center, here LEM in Bulgaria (Sofia)
- ❑ “17” means the year of the production, here the year 2017
- ❑ “206” means the day of the production, here the 206<sup>th</sup> day of the year 2017 (25<sup>th</sup> July 2017)

**Change 2:**

Supplier for some machining of these plastic parts.

**Concerned products for Change 2:**

**LV 100/SP25;**

**LV 100/SP60;**

**LV 100/SP71; LV 100/SP73; LV 100/SP77;**

**LV 100/SP82;**

**LV 100-250/SP5;**

we confirm you that LEM is now producing **some of the models, listed here above according to the change 2** explained here above and since the following date codes:

- date code **817189** for the models **LV 100/SP25; LV 100/SP60; LV 100/SP71; LV 100/SP73; LV 100/SP77;**
- date code **817196** for the model **LV 100/SP82**
- **LV 100-250/SP5: at a later date**

Just few explanation on the date code (example with the date code 817189):

- ☐ “8” means the production center, here LEM in Bulgaria (Sofia)
- ☐ “17” means the year of the production, here the year 2017
- ☐ “189” means the day of the production, here the 189<sup>th</sup> day of the year 2017 (08<sup>th</sup> July 2017)

➤ ***Reason of the technical changes:***

Securing supply chain

**Impact on the product:**

- ☐ On the form: NO
- ☐ On the fit: NO
- ☐ On the function: NO
- ☐ On the reliability: NO

**Schedule of the modification:**

|                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-----------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Start of delivery of modified products</p> | <p><b>Change 1:</b></p> <ul style="list-style-type: none"> <li>- date code 817155 (04<sup>th</sup> June 2017 in LEM Bulgaria): see concerned models on pages 1 and 2</li> <li>- date code 817206 (25<sup>th</sup> July 2017 in LEM Bulgaria): see concerned models on page 3</li> <li>- <b>date code 117296 (23<sup>rd</sup> October 2017 in LEM Geneva) for LV 100-4200</b></li> </ul> <p><b>Change 2:</b></p> <ul style="list-style-type: none"> <li>- date code 817189 (08<sup>th</sup> July 2017) LV 100/SP25; LV 100/SP60; LV 100/SP71; LV 100/SP73; LV 100/SP77;</li> <li>- date code 817196 (15<sup>th</sup> July 2017) for LV 100/SP82</li> <li>- LV 100-250/SP5: at a later date</li> </ul> |
|-----------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

Sincerely yours,  
Stéphane ROLLIER  
Product Manager